

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | | |
|--|--|
| <p>1. Name of the Officer</p> <p>2. Name of the School</p> <p>3. Location with name of Education District/ Sub. District</p> <p>4. Classification of Building as specified in column 4 of the application for fitness certificate and size.</p>

<p>5. Period for which the certificate is issued</p> <p>6. Nature of defects , if any</p> <p style="margin-left: 20px;">a) Foundation and basement</p> <p style="margin-left: 20px;">b) Superstructure</p> <p style="margin-left: 20px;">c) Doors and Windows</p> <p style="margin-left: 20px;">d) Wood work wrought and put up</p> <p style="margin-left: 20px;">e) Roof</p> <p style="margin-left: 20px;">f) Flooring</p> <p style="margin-left: 20px;">g) Miscellaneous (Cracks, etc.)</p> <p>7. Any major defects noticed which will render the building unsafe in any manner</p>

<p>8. Whether maintenance works have been done properly</p> <p>9. Whether the structure is sound or not for conducting classes</p> | <p>Sreejith Kumar MS</p> <p>Holy Face School, Makkiyad</p> <p>Mananthavady, Edo. Sub. District</p> <p>Kalpetta Edo. District - Main Block</p> <p>1. 6.40 x 6.90 x 3.70 = 9 Nos of GF</p> <p>2. 9.50 x 6.40 x 3.70 = 2 Nos of GF</p> <p>3. 6.40 x 6.90 x 3.70 = 10 Nos of FF</p> <p>4. 9.50 x 6.40 x 3.70 = 2 Nos of FF</p> <p>5. 6.40 x 6.90 x 2.70 = 10 Nos of SF</p> <p>6. 9.50 x 6.40 x 3.70 = 2 Nos of F</p> <p style="margin-left: 20px;">width 2.20m wide veranda</p>
<p style="text-align: center;">BLOCK B</p> <p>1. 8.35 x 6.42 x 3.70 = 3 Nos of GF</p> <p>2. 9.42 x 6.95 x 3.70 = 1 Nos of GF</p> <p>3. 8.35 x 6.95 x 3.70 = 3 Nos of FF</p> <p>4. 9.42 x 6.95 x 3.70 = 1 Nos of FF</p> <p>5. 8.53 x 6.42 x 3.70 = 3 Nos of SF</p> <p>6. 9.42 x 6.95 x 3.70 = 1 Nos of SF</p>
<p style="text-align: center;">No</p>
<p style="text-align: center;">Yes</p> |
|--|--|


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 07.02.2024 and found to be fit / unfit to conduct classes, for the period 2023-2024 for the reasons stated above.

Place : Mananthavady
 Date : 07.02.2024

Alm
PRINCIPAL
 HOLY FACE ENGLISH SCHOOL
 MAKKIYAD - 670 731
 WAYANAD DISTRICT



Sreejith
ASST. ENGINEER
 LSGD, Section
 Mananthavady Grama Panchayat